RECLAMATION -REMEDIATION BID **PACKAGE**

BID PACKAGE NO. 2

BID PACKAGE NUMBER 2

Reclamation-Remediation Clean-up Bid Package No. 2

COUNTY:

AMITE:

WELL NAME	FIELD	API	LAT	TONG
N E I 34-10 1	GILLSBURG	23-005-20451	31.005414	-90.586658
UNIDENTIFIED	GILLSBURG	300	31.01552	-90.58843
UNIDENTIFIED	GILLSBURG	90	31.01595	-90.591367
UNIDENTIFIED	GILLSBURG	3	31.01275	-90.591369
UNIDENTIFIED	GILLSBURG	·	31.01552	-90.58843

LINCOLN:

UNIDENTIFIED	SWEETWATER	,	31.387163	-90.377096
34-51	CENTER POINT	23-085-20090		31.446495

CLEANUP STATUS

Lat	Long	API # if any	Well Name if known	Well#	County	Field	Scope of Work	Package	е
31.005414	-90.586658	2300520451	NEI 34-10	1	AMITE	Gillsburg Field	Concrete slabs needs to be removed, disposed and location restored	d	2
31.01552	-90.58843				AMITE	Gillsburg Field	2 Tanks, one Treater, Pump slab and piping need to be removed, disposed and location restored.		2
31.01595	-90.591367				AMITE	Gillsburg Field	2 tanks need to be removed, disposed and location restored.		2
31.01275	-90.591369				AMITE	Gillsburg Field	Seven tanks need to be removed, disposed and location restored.		2
31.01552	-90.58843				AMITE	Gillsburg Field	(Casey Little property) Two tanks, one treater, pump slab and piping need to be removed, disposed and location restored.	5	2
31.387163	-90.377096				LINCOLN	Sweetwater Field	(Brad Davis property) Has three tanks, one treater pump slab, and piping need to be removed, disposed and location restored.		2
31.446495	-90.597516	2308520090	MCGEE 34-5	1	LINCOLN	Center Point	3 tanks, pump slab need to be removed, disposed and location restored. Casing at ground level with plate welded needs to be cut off below plow depth, plate welded on top and covered with location restored.		2