DBT 4800-L

Danger

H314 : Causes severe skin burns and eye damage
H318 : Causes serious eye damage

P260 : Do not breathe vapors, mist, or spray.
P264 : Wash hands, forearms, and other exposed areas thoroughly after handling.
P280 : Wear protective gloves, protective clothing, and eye protection.
P301+P330+P331 : If swallowed: rinse mouth. Do NOT induce vomiting.
P303+P361+P353 : If on skin (or hair): Take off immediately all contaminated clothing. Rinse skin with water/shower.
P304+P340 : IF INHALED: Remove person to fresh air and keep at rest in a position comfortable for breathing.
P305+P351+P338 : IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.
P310 : Immediately call a poison center or doctor.
P321 : Specific treatment (see section 4 on this SDS).
P363 : Wash contaminated clothing before reuse.
P405 : Store locked up.
P501 : Dispose of contents/container in accordance with local, regional, national, and international regulations.

Delta Chemical Corp.
The Difference in Water Treatment
P.O. Box 7430
Metaire, LA 70010

Delta Chemical Corporation
P.O. Box 7430
Metairie, LA 70010-7430
USA
1 504 733 0630

Emergency number : Chem Tel - 1 800-255-3924