

WELL NAME: E T DAUGHDRILL 1

COUNTY: JEFFERSON DAVIS

FIELD: GWINVILLE

SECTION. 33 TWN. 9 N RANGE 19 W

LAT. 31.70318 LONG. -89.9128

API # 23-065-00015

BASE OF USDW:

FILL IN TWO COPIES OF THIS WITH TYPEWRITER

STATE OF MISSISSIPPI

STATE OIL AND GAS BOARD


Serial No. **3487**

LOG OF WELL

Gulf Refining Company
Gulf Production Division

FIELD **Grinville** COMPANY **Gulf Refining Company**
County **Jefferson Davis** Section **33** Township **9N** Range **19W** Elevation **466.4' Gr.**
Location of well (Distances from corner) **554'S. and 553'W. of N.E. Corner of N.W. 1/4 of S.E. 1/4**
Farm **E. T. Daughdrill** Well No. **1** Permit No. **3487**

The information given herewith is a complete record of the well and all work done thereon so far as can be determined from all available records.

Signed  _____

Date **July 31** 19 **47** Title **Supt. of Prod.**

The summary on this page is for ORIGINAL condition of well at above date.

Commenced Drilling **May 12** 19 **47** Finished Drilling **June 11** 19 **47**

OIL OR GAS ZONES

No. 1 From **None** to _____ No. 4 From _____ to _____
No. 2 From _____ to _____ No. 5 From _____ to _____
No. 3 From _____ to _____ No. 6 From _____ to _____

IMPORTANT WATER SANDS

No. 1 From _____ to _____ No. 3 From _____ to _____
No. 2 From _____ to _____ No. 4 From _____ to _____

CASING RECORD

Size	Wt. per Foot	Threads Per in.	Make	Where Landed	Cemented			From	To	Bailed Dry	Stood Hrs.
					Yes	No	Sacks				
0-3/4"	40.50#	8	National	1667'	Yes		765			Yes	48

LINER RECORD

Size **None** Weight _____ lbs. _____ Ft. _____ In. Blank _____ Ft. _____ In. Perforated _____
Mudded well from _____ to _____ and from _____ to _____
Purpose: _____
Rotary Tools were used from **0** to **8397'** and from _____ to _____
Standard Tools were used from _____ to _____ and from _____ to _____
Put to producing **Dry Hole** 19 Production for first 24 hours was _____ bbl. of
which _____ % was oil, _____ % was water and _____ % was Base Sediment.
Gravity of Oil _____ ° Be. Gas with oil _____ cu. ft.
If Gas Well, cu. ft. per 24 hrs. _____ Gallons gasoline per 1000 cu. ft. gas _____
Rock pressure _____ lbs. per sq. in.

L. C. Smith

Driller.

A. F. Lee

Driller.

R. F. Schutte

Driller.

Patrick Drilling Company
Contractor

Driller.

23-065-00015

GWINVILLE

STATE OIL AND GAS BOARD

3487 Depth 8,391' ^{8,391' S.H.L.} Gr. Elev. 466.4' DF 471'
 Farm E. T. Daughdrill Well No. 1 D. Log Yes E. Log Yes
 Operator I. Gulf Refining Company
 Location 554' S. & 553' W. of N. E. Corner of NW $\frac{1}{4}$ of
 SE $\frac{1}{4}$ Sec. 33 Tp. 9N R. 19W
 County Jeff Davis Permit Issued 19
 Commenced May 12 1947 Completed June 11 19 47
 Sands _____ to _____ Sands _____ to _____
 _____ to _____
 _____ to _____
 Init. Prod. _____ bbl.
 Gas _____ cu. ft.
 Put to Prod. _____
 Gravity _____
 Remarks D & A
 Aban. _____ 19
 Reworked _____ Completed _____

FORMATION TOPS

CATAHOULA _____
 VICKSBURG _____
 YAZOO _____
 MOODY'S BRANCH _____
 Cmt. 1785
 COCKFIELD _____
 CAMERINA LIME 1826
 SPARTA 1931
 ZILPHA 2540
 WINONA 2683
 TALLAHATTA _____
 WILCOX 2928
 M.D. 6105
 CLAYTON _____

CHALK OR SELMA—

ELITAW—

B ch.

TUSCALOOSA

6806

7967

GWINVILLE

STATE OIL AND GAS BOARD

STATE OF MISSISSIPPI

Application

Permit to Drill, Deepen, or Plug

or Perforate


Serial No.

3487

NORTH

NW 1/4

NE 1/4



SW 1/4

SE 1/4

SINGLE SECTION PLAT

640 Acres

Mark Well Accurately on Section Plat Shown Above. Two typewritten copies of the log of each well on Board forms must be filed with this office not later than 15 days after completion of drilling.

(1) Date

March 7th

1947

NOTICE—To drill, deepen, abandon, or perforate a well in Mississippi without first securing a written permit, is an infraction of the law and subject to prosecution.

(2) County Jefferson Davis (Gwinville)

(3) Farm E.T. Daughdrill Well No. 1

(4) Sec. 33 T. 9 N. R. 19 W.

(5) Land Owner E.T. Daughdrill and wife,

Gulf Refg. Co.

(6) Owner of Well Gulf Prod. Division

(7) Address Shreveport, La.

(8) Permit to Drill

Drill, Deepen, Abandon, Plug, and Perforate

(9) Oil, Gas or Test Well Distillate

(10) Location of Well in feet from some corner in the Section 554' South and 553' West of N.E. Corner of N.W. 1/4

of S.E. 1/4 of section

(11) Send Permit to Mr. L.H. Moore

Name

P.O. Box 1731, Shreveport, La.

Address