

Stennis International Airport Aircraft Hangar Facility Gate Repair

Scope of Work

The existing motor operated gate does work. The gate operator needs to be repaired so that it is operational again. The existing gate operator is a HY-Security Slide Driver, Model 222 ST SS that was installed July, 25, 2006. The work includes provide all necessary parts, labor and materials necessary to make the gate operator operational.

Any technical questions regarding the work contact John Stein, P.E., Digital Engineering at (228)463-0130 or jstein@deii.net.

To arrange a site visit, please contact Roland from Selex Galieo at (228)493-0403.

