

Light Production (D95/110/125/136-4595-4110-4112/27) Copier/Printers

Current Changes

LTPRODS-M

Light Production (D95/110/125/136) Price List Equipment Sale & Maintenance Price List

Current Changes

Light Production (D95/110/125/136-4595-4110-4112/27) Copier/Printers

Xerox Form Number	Issue Date	Price List Name	Reason Changed
Sales and Mainte	nance		
LTPRODS-M	11/01/16	Light Production (4595-4110/12/27, D95/110/125/136) Equipment Sale and Maintenance Price List	GIGABIT accessory market code kit roll 497k06792 to 497k06793
			Dell Monitor roll on mainframes FFSRVR and FFSRVR136 (YEB to 8RX)



Market Code/ Product Code				Produc	t Descr	iption			Purchase Price \$
	For informatic								
	http://xww.docu	usnare	e.worio	a.xerox	.com/a	SWED/VIE	w/Colle	<u>ction-354191</u>	
Xerox D95 C	opier/Printer								
Carrier	delivered/installed except wher	re noted	l; CSE r	equired v	when pai	ticular acc	essories a	are ordered.	
	orders should be processed in								
D95CP	D95 Copier/Printer (BG2) w					nt Mount K	it (497K0)	9110), MSI Bypass Tray	\$46,500
	(497K09130), Customer Doc This configuration represents mo	umenta	ation &	Software	Kit (650	0k33610),			, ,
You Must Choo	se ONE of the Following:								
100PPMKIT	100 PPM Kit (BY0), Initializat						d Account	ing, USB enablement.	N/C
	Only available for new insta	alls, no	t availa	able pos	t instal				
	se ONE of the Following:								
MLA	Standard (Staple) Finisher with			ınch					6,550
ткх	Booklet Finisher w/ 2/3 Hole	Punch							11,800
	se ONE of the Following:								
BYPASS	Bypass Chute (497K02520)								350
HIGHCAPFD	High Capacity Feeder (ACH,								2,700
OVRSZHCF	Oversized High Capacity Fee	eder (Al	KC, 498	3K15381	, 498K1	8310) <mark>CS</mark>	E Requir	ed for install	4,000
	se ONE of the Following:								
INSTSECUR	Restricted Access Install (NA					vith secu	rity requi	rements that do not allow	120
	the use of flash media [don		nsite- e	.g. GSA)				
INSTSTD	Standard Install (497K10900))							N/C
	se ANY of the Following:								
CAC-KIT	Common Access Card Enabl	lement	Kit (497	7K04790).				199
FIDEVICE2	Foreign Interface Device (498		1) CS	E Requi	red for i	nstall			150
GIGABIT	Gigabit Ethernet Kit (497k067								400
	Requires ESD Prot		Kit (Gl	ROUND	ESD) ac	cessory			
GROUNDESD	ESD Protection Kit (497K109								N/C
							only 1 nee	eded per Copier/Printer.	15.000
INTEGSFT	Integrated SquareFold Trimm						D		15,000
	Only available for u			kiet Finis	sher w/	2/3 Hole	Punch (I	КХ)	05
LEFT-UI	Left UI Kit (497K07290, 497k								85
MUA PDFKIT2	C/Z Folder CSE Required f		all						5,700
SECRWATR	PDF Kit (497K09140, 497K09 Secure Watermark Kit (497k0								2,850 995
STAPLER2	Convenience Stapler (498K0								299
USBHUB	USB HUB Kit (497K06750)		auired	for inst	all				150
			-			foaturo fe	or the Ye	ox D95/110/125 Copier/Print	
								'Accessory Only' order in V	
JBAKIT2	Job Based Accounting (497K							According only of the interview	500
0D/ IIII 2		(00100)	/						000
497K05270	Mobility Plate. See below								N/C
		uipment	Service		HCF-2	OHCF -1	OHCF -2		
	Cor	mponent	Plates	ют	tray	Tray	Tray		
	#	Plates	3	2	1	2	2		
		uipment	IEM	ORC	HCC	oz Felder	D4 finaibar		
		Plates	IFM 1	GBC 1	HCS 2	cz Folder 1	finsiher 2		
		uipment	DS	Sauero					
		uipment mponent	D5 Booklet	Square Folder	D5 For		Таре		
	#	Plates	Finisher 2	Trimmer 1	PFIM 2	PFIM 2	Binder 2		



Market Code/	Product Description	Purchase
Product Code		Price \$
<u>Xerox D110 /</u>	<u>/ D125 Copier/Printer</u>	
Carrier	delivered/installed except where noted; CSE required when particular accessories are ordered.	
• The D11	0/D125 orders should be processed in SPA and routed accordingly.	
D110CP	D110 Copier/Printer (BG0) with Speed Badge (BY1), Initialization Kit (Dongle) (497K14530), Job Based	\$56,500
	Accounting, USB enablement, FCW UI C/P (XRR), UI Right Mount Kit (497K09110), MSI Bypass Tray (497K09130), Customer Documentation & Software Kit (650k33610), Nationalization Kit (650K34451).	• ,
	This configuration represents most current shippable version level 08.	
D125CP	D125 Copier/Printer (BG0) with Speed Badge (BY3), Initialization Kit (Dongle) (497K14550), Job Based Accounting, USB enablement, FCW UI C/P (XRR), UI Right Mount Kit (497K09110), MSI Bypass Tray (497K09130), Customer Documentation & Software Kit (650k33610), Nationalization Kit (650K34451). <i>This configuration represents most current shippable version level 08.</i>	\$69,500
You Must Choo	se ONE of the Following:	
BYPASS	Bypass Chute (497K02520)	350
	High Capacity Feeder (ACH, 498K10700)	2,700
OVRSZHCF	Oversized High Capacity Feeder (AKC, 498K15381, 498K18310). CSE Required for install	4,000
	2 Tray Oversize High Capacity Feeder (B98, 498K18310) - Carrier Install	6,500
You Must Choo	se ONE of the Following:	
	Restricted Access Install (NA8) (Required for customers with security requirements that do not allow the use of flash media [dongle] onsite- e.g. GSA)	120
	Standard Install (497K10900)	N/C
	se AT LEAST ONE of the Following:	
	Interface Module (MAX, 498K18310)	2,000
	 cannot be purchased as a standalone finishing option. See further product combination notations below 	2,000
MLA	Standard (Staple) Finisher with 2/3 Hole Punch	6,550
STACKER	High Capacity Stacker with one dolly cart (MAY), Interface Module Power Cord (498K18310), Interface Cable Middle (498K16770)	13,000
STDFINPLS	Requires purchase of INTERFACE accessory Standard Finisher Plus (Partner Interface Finishing Module) (XMH, XBR, 497K12770, 498K18310, 497K06850)	12,000
	 Requires purchase of INTERFACE accessory Required when purchasing TAPE-BIND or TXC's eBinder or TXC's RCT Pro30 If purchasing both TAPE-BIND and TXC's Pro 30 for a 'chained' finishing solution, only ONE STDFINPLS is needed in total. CSE Required for install 	
TAPE-BIND	Tape Binder (HWX, 650K30110) Requires purchase of Partner Finishing Interface Module (STDFINPLS) accessory CSE Required for install	15,000
ТКХ	Booklet Finisher w/ 2/3 Hole Punch	11,800
You May Choos	se ANY of the Following:	
ADV-PUNCH	 GBC Advanced Punch (498K18950, UAD, 497N00216) Requires Interface Module (INTERFACE) accessory Also requires purchase of either a Staple Finisher w/ 2/3 Hole Punch (MLA) or Booklet 	12,400
	Finisher w/ 2/3 Hole Punch (TKX) or High Capacity Stacker (STACKER)	
CAC-KIT	Common Access Card Enablement Kit (497K04790).	199
FIDEVICE2	Foreign Interface Device (498K14141) CSE Required for install	150
GIGABIT	Gigabit Ethernet Kit (497k06793) • Requires ESD Protection Kit (GROUBNESD) accessory	400
GROUNDESD	ESD Protection Kit (497K10920) Required with every VSELFFPS or GIGABIT purchase. Only 1 needed per Copier/Printer. 	N/C
HCSUIFA INTEGSFT	HCS UI Fixed Angle (498K17820) Integrated SquareFold Trimmer (498K18310, TLX, 650K31900) • only available for use with Booklet Finisher w/ 2/3 Hole Punch (TKX)	N/C 15,000
LEFT-UI	Left UI Kit (497K07290, 497K09120)	85
LUI2TOHCF	Oversize HCF 2T FCW UI Mount Kit (497K07300)	N/C
MUA	C/Z Folder CSE Required for install	5,700



Market Code/ Product Code	Product Description				
PDFKIT2	PDF Kit (497K09140, 497K09150)	2,850			
SECRWATR	Secure Watermark Kit (497k09170)	995			
STAPLER2	Convenience Stapler (498K08250)	299			
USBHUB	USB HUB Kit (497K06750) CSE Required for install	150			
XSISRH9B	XSIS Removable Hard Drive – Install Kit (497K10210)	3,000			
XSISED9B	XSIS Removable Hard Drive IOT Only – Extra Drive Set (497K10220)	1,500			
	14, Job Based Accounting (JBA) will ship as a standard feature for the Xerox D95/110/125 Copier/Printe				
	. This optional kit will remain for MIF customers and can be ordered via an 'Accessory Only' order in Va				
JBAKIT2	Job Based Accounting (497K09160)	500			
JDANIZ	Job Dased Accounting (497 (09100)	500			
497K05270	Mobility Plate See below	N/C			
4371(03270		10/0			
	Equipment Service IOT HCF-2 OHCF-1 OHCF-2 Component Plates IOT tray Tray Tray				
	#Plates 3 2 1 2 2				
	Equipment D4				
	Equipment D4 Component IFM GBC HCS cz Folder finsiher				
	#Plates 1 1 2 1 2				
	Equipment D5 Square				
	Component Booklet Folder D5 For Tape				
	Finisher Trimmer PFIM PFIM Binder				
Xerox D136	Copier/Printer				
	delivered/installed except where noted; CSE required when particular accessories are ordered.				
	36 orders should be processed in SPA and routed accordingly.				
D136CP	D136 Copier/Printer (A0D), Full Color Web UI (XRR), Initialization Kit (497K15260), Interface Cooling	82,000			
	Module (A7D), Power Cord (498K18310), Job Based Accounting, USB Enablement, UI Right Mount Kit				
	(497K09110), Multi-Sheet Insert Bypass Tray (497K09130), Customer Documentation & Software Kit				
	(650K33610), Nationalization Kit (650K34441).				
	This configuration represents most current shippable version level 05.				
	ose ONE of the Following:				
BYPASS	Bypass Chute (497K02520)	350			
HICAP136	High Capacity Feeder w/ Wing Table (A8D, 498K10700)	2,700			
OVRSZHF2	2 Tray Oversize High Capacity Feeder (B98, 498K18310) - Carrier Install	6,500			
You Must Choo	ose ONE of the Following:				
	Restricted Access Install (NA8) (Required for customers with security requirements that do not allow	120			
INSISECUR					
INSTSECUR		120			
	the use of flash media [dongle] onsite- e.g. GSA)				
INSTSTD	the use of flash media [dongle] onsite- e.g. GSA) Standard Install (497K10900)	N/C			
INSTSTD You Must Choo	the use of flash media [dongle] onsite- e.g. GSA) Standard Install (497K10900) ose <u>AT LEAST ONE</u> of the Following:	N/C			
INSTSTD You Must Choo MLA	the use of flash media [dongle] onsite- e.g. GSA) Standard Install (497K10900) ose AT LEAST ONE of the Following: Standard (Staple) Finisher with 2/3 Hole Punch	N/C 6,550			
INSTSTD You Must Choo MLA STACKER	the use of flash media [dongle] onsite- e.g. GSA) Standard Install (497K10900) ose AT LEAST ONE of the Following: Standard (Staple) Finisher with 2/3 Hole Punch High Capacity Stacker with one dolly cart (MAY), Interface Module Power Cord (498K18310), Interface Cable Middle (498K16770)	N/C 6,550 13,000			
INSTSTD You Must Choo MLA	the use of flash media [dongle] onsite- e.g. GSA) Standard Install (497K10900) ose AT LEAST ONE of the Following: Standard (Staple) Finisher with 2/3 Hole Punch High Capacity Stacker with one dolly cart (MAY), Interface Module Power Cord (498K18310), Interface Cable	N/C 6,550			
INSTSTD You Must Choo MLA STACKER	the use of flash media [dongle] onsite- e.g. GSA) Standard Install (497K10900) Se AT LEAST ONE of the Following: Standard (Staple) Finisher with 2/3 Hole Punch High Capacity Stacker with one dolly cart (MAY), Interface Module Power Cord (498K18310), Interface Cable Middle (498K16770) Standard Finisher Plus (Partner Interface Finishing Module) (XMH, XBR, 497K12770, 498K18310,	N/C 6,550 13,000			
INSTSTD You Must Choo MLA STACKER	the use of flash media [dongle] onsite- e.g. GSA) Standard Install (497K10900) See AT LEAST ONE of the Following: Standard (Staple) Finisher with 2/3 Hole Punch High Capacity Stacker with one dolly cart (MAY), Interface Module Power Cord (498K18310), Interface Cable Middle (498K16770) Standard Finisher Plus (Partner Interface Finishing Module) (XMH, XBR, 497K12770, 498K18310, 497K06850) • Required when purchasing TAPE-BIND or TXC's eBinder or TXC's RCT Pro30	N/C 6,550 13,000			
INSTSTD You Must Choo MLA STACKER	the use of flash media [dongle] onsite- e.g. GSA) Standard Install (497K10900) Se AT LEAST ONE of the Following: Standard (Staple) Finisher with 2/3 Hole Punch High Capacity Stacker with one dolly cart (MAY), Interface Module Power Cord (498K18310), Interface Cable Middle (498K16770) Standard Finisher Plus (Partner Interface Finishing Module) (XMH, XBR, 497K12770, 498K18310, 497K06850)	N/C 6,550 13,000			
INSTSTD You Must Choo MLA STACKER	the use of flash media [dongle] onsite- e.g. GSA) Standard Install (497K10900) ose AT LEAST ONE of the Following: Standard (Staple) Finisher with 2/3 Hole Punch High Capacity Stacker with one dolly cart (MAY), Interface Module Power Cord (498K18310), Interface Cable Middle (498K16770) Standard Finisher Plus (Partner Interface Finishing Module) (XMH, XBR, 497K12770, 498K18310, 497K06850) • Required when purchasing TAPE-BIND or TXC's eBinder or TXC's RCT Pro30 • If purchasing both TAPE-BIND and TXC's Pro 30 for a 'chained' finishing solution, only ONE STDFINPLS is needed in total.	N/C 6,550 13,000			
INSTSTD You Must Choo MLA STACKER STDFINPLS	the use of flash media [dongle] onsite- e.g. GSA) Standard Install (497K10900) ose AT LEAST ONE of the Following: Standard (Staple) Finisher with 2/3 Hole Punch High Capacity Stacker with one dolly cart (MAY), Interface Module Power Cord (498K18310), Interface Cable Middle (498K16770) Standard Finisher Plus (Partner Interface Finishing Module) (XMH, XBR, 497K12770, 498K18310, 497K06850) • Required when purchasing TAPE-BIND or TXC's eBinder or TXC's RCT Pro30 • If purchasing both TAPE-BIND and TXC's Pro 30 for a 'chained' finishing solution, only ONE STDFINPLS is needed in total. • CSE Required for install	N/C 6,550 13,000 12,000			
INSTSTD You Must Choo MLA STACKER	the use of flash media [dongle] onsite- e.g. GSA) Standard Install (497K10900) ose AT LEAST ONE of the Following: Standard (Staple) Finisher with 2/3 Hole Punch High Capacity Stacker with one dolly cart (MAY), Interface Module Power Cord (498K18310), Interface Cable Middle (498K16770) Standard Finisher Plus (Partner Interface Finishing Module) (XMH, XBR, 497K12770, 498K18310, 497K06850) • Required when purchasing TAPE-BIND or TXC's eBinder or TXC's RCT Pro30 • If purchasing both TAPE-BIND and TXC's Pro 30 for a 'chained' finishing solution, only ONE STDFINPLS is needed in total. • CSE Required for install Tape Binder (HWX, 650K30110)	N/C 6,550 13,000			
INSTSTD You Must Choo MLA STACKER STDFINPLS	the use of flash media [dongle] onsite- e.g. GSA) Standard Install (497K10900) ose AT LEAST ONE of the Following: Standard (Staple) Finisher with 2/3 Hole Punch High Capacity Stacker with one dolly cart (MAY), Interface Module Power Cord (498K18310), Interface Cable Middle (498K16770) Standard Finisher Plus (Partner Interface Finishing Module) (XMH, XBR, 497K12770, 498K18310, 497K06850) • Required when purchasing TAPE-BIND or TXC's eBinder or TXC's RCT Pro30 • If purchasing both TAPE-BIND and TXC's Pro 30 for a 'chained' finishing solution, only ONE STDFINPLS is needed in total. • CSE Required for install Tape Binder (HWX, 650K30110) • Requires purchase of Partner Finishing Interface Module (STDFINPLS) accessory	N/C 6,550 13,000 12,000			
INSTSTD You Must Choo MLA STACKER STDFINPLS	the use of flash media [dongle] onsite- e.g. GSA) Standard Install (497K10900) ose AT LEAST ONE of the Following: Standard (Staple) Finisher with 2/3 Hole Punch High Capacity Stacker with one dolly cart (MAY), Interface Module Power Cord (498K18310), Interface Cable Middle (498K16770) Standard Finisher Plus (Partner Interface Finishing Module) (XMH, XBR, 497K12770, 498K18310, 497K06850) • Required when purchasing TAPE-BIND or TXC's eBinder or TXC's RCT Pro30 • If purchasing both TAPE-BIND and TXC's Pro 30 for a 'chained' finishing solution, only ONE STDFINPLS is needed in total. • CSE Required for install Tape Binder (HWX, 650K30110) • Requires purchase of Partner Finishing Interface Module (STDFINPLS) accessory • CSE Required for install	N/C 6,550 13,000 12,000 15,000			
INSTSTD You Must Choo MLA STACKER STDFINPLS TAPE-BIND	the use of flash media [dongle] onsite- e.g. GSA) Standard Install (497K10900) ose AT LEAST ONE of the Following: Standard (Staple) Finisher with 2/3 Hole Punch High Capacity Stacker with one dolly cart (MAY), Interface Module Power Cord (498K18310), Interface Cable Middle (498K16770) Standard Finisher Plus (Partner Interface Finishing Module) (XMH, XBR, 497K12770, 498K18310, 497K06850) • Required when purchasing TAPE-BIND or TXC's eBinder or TXC's RCT Pro30 • If purchasing both TAPE-BIND and TXC's Pro 30 for a 'chained' finishing solution, only ONE STDFINPLS is needed in total. • CSE Required for install Tape Binder (HWX, 650K30110) • Requires purchase of Partner Finishing Interface Module (STDFINPLS) accessory • CSE Required for install Booklet Finisher w/ 2/3 Hole Punch	N/C 6,550 13,000 12,000			
INSTSTD You Must Choo MLA STACKER STDFINPLS TAPE-BIND TKX You May Choo	the use of flash media [dongle] onsite- e.g. GSA) Standard Install (497K10900) ose AT LEAST ONE of the Following: Standard (Staple) Finisher with 2/3 Hole Punch High Capacity Stacker with one dolly cart (MAY), Interface Module Power Cord (498K18310), Interface Cable Middle (498K16770) Standard Finisher Plus (Partner Interface Finishing Module) (XMH, XBR, 497K12770, 498K18310, 497K06850) • Required when purchasing TAPE-BIND or TXC's eBinder or TXC's RCT Pro30 • If purchasing both TAPE-BIND and TXC's Pro 30 for a 'chained' finishing solution, only ONE STDFINPLS is needed in total. • CSE Required for install Tape Binder (HWX, 650K30110) • Requires purchase of Partner Finishing Interface Module (STDFINPLS) accessory • CSE Required for install Booklet Finisher w/ 2/3 Hole Punch	N/C 6,550 13,000 12,000 15,000 11,800			
INSTSTD You Must Choo MLA STACKER STDFINPLS TAPE-BIND TKX You May Choo	the use of flash media [dongle] onsite- e.g. GSA) Standard Install (497K10900) pse AT LEAST ONE of the Following: Standard (Staple) Finisher with 2/3 Hole Punch High Capacity Stacker with one dolly cart (MAY), Interface Module Power Cord (498K18310), Interface Cable Middle (498K16770) Standard Finisher Plus (Partner Interface Finishing Module) (XMH, XBR, 497K12770, 498K18310, 497K06850) • Required when purchasing TAPE-BIND or TXC's eBinder or TXC's RCT Pro30 • If purchasing both TAPE-BIND and TXC's Pro 30 for a 'chained' finishing solution, only ONE STDFINPLS is needed in total. • CSE Required for install Tape Binder (HWX, 650K30110) • Requires purchase of Partner Finishing Interface Module (STDFINPLS) accessory • CSE Required for install Booklet Finisher w/ 2/3 Hole Punch se ANY of the Following: GBC Advanced Punch (498K18950, UAD, 497N00216)	N/C 6,550 13,000 12,000 15,000			
INSTSTD You Must Choo MLA STACKER STDFINPLS TAPE-BIND TKX You May Choo	the use of flash media [dongle] onsite- e.g. GSA) Standard Install (497K10900) pse AT LEAST ONE of the Following: Standard (Staple) Finisher with 2/3 Hole Punch High Capacity Stacker with one dolly cart (MAY), Interface Module Power Cord (498K18310), Interface Cable Middle (498K16770) Standard Finisher Plus (Partner Interface Finishing Module) (XMH, XBR, 497K12770, 498K18310, 497K06850) • Required when purchasing TAPE-BIND or TXC's eBinder or TXC's RCT Pro30 • If purchasing both TAPE-BIND and TXC's Pro 30 for a 'chained' finishing solution, only ONE STDFINPLS is needed in total. • CSE Required for install Tape Binder (HWX, 650K30110) • Requires purchase of Partner Finishing Interface Module (STDFINPLS) accessory • CSE Required for install Booklet Finisher w/ 2/3 Hole Punch Se ANY of the Following: GBC Advanced Punch (498K18950, UAD, 497N00216) • Also requires purchase of either a Staple Finisher w/ 2/3 Hole Punch (MLA) or Booklet	N/C 6,550 13,000 12,000 15,000 11,800			
INSTSTD You Must Choo MLA STACKER STDFINPLS TAPE-BIND TKX You May Choo ADV-PUNCH	the use of flash media [dongle] onsite- e.g. GSA) Standard Install (497K10900) pse AT LEAST ONE of the Following: Standard (Staple) Finisher with 2/3 Hole Punch High Capacity Stacker with one dolly cart (MAY), Interface Module Power Cord (498K18310), Interface Cable Middle (498K16770) Standard Finisher Plus (Partner Interface Finishing Module) (XMH, XBR, 497K12770, 498K18310, 497K06850) • Required when purchasing TAPE-BIND or TXC's eBinder or TXC's RCT Pro30 • If purchasing both TAPE-BIND and TXC's Pro 30 for a 'chained' finishing solution, only ONE STDFINPLS is needed in total. • CSE Required for install Tape Binder (HWX, 650K30110) • Requires purchase of Partner Finishing Interface Module (STDFINPLS) accessory • CSE Required for install Booklet Finisher w/ 2/3 Hole Punch Se ANY of the Following: GBC Advanced Punch (498K18950, UAD, 497N00216) • Also requires purchase of either a Staple Finisher w/ 2/3 Hole Punch (MLA) or Booklet Finisher w/ 2/3 Hole Punch (TKX) or High Capacity Stacker (STACKER)	N/C 6,550 13,000 12,000 15,000 11,800 12,400			
INSTSTD You Must Choo MLA STACKER STDFINPLS TAPE-BIND	the use of flash media [dongle] onsite- e.g. GSA) Standard Install (497K10900) pse AT LEAST ONE of the Following: Standard (Staple) Finisher with 2/3 Hole Punch High Capacity Stacker with one dolly cart (MAY), Interface Module Power Cord (498K18310), Interface Cable Middle (498K16770) Standard Finisher Plus (Partner Interface Finishing Module) (XMH, XBR, 497K12770, 498K18310, 497K06850) • Required when purchasing TAPE-BIND or TXC's eBinder or TXC's RCT Pro30 • If purchasing both TAPE-BIND and TXC's Pro 30 for a 'chained' finishing solution, only ONE STDFINPLS is needed in total. • CSE Required for install Tape Binder (HWX, 650K30110) • Requires purchase of Partner Finishing Interface Module (STDFINPLS) accessory • CSE Required for install Booklet Finisher w/ 2/3 Hole Punch Se ANY of the Following: GBC Advanced Punch (498K18950, UAD, 497N00216) • Also requires purchase of either a Staple Finisher w/ 2/3 Hole Punch (MLA) or Booklet	N/C 6,550 13,000 12,000 15,000 11,800			



Market Code/ Product Code				
GIGABIT	Gigabit Ethernet Kit (497k067	93)		400
	Requires ESD Prote	ection Kit (GF	ROUBNESD) accessory	
GROUNDESD	ESD Protection Kit (497K109)	20)		N/C
	Required with every	VSELFFPS	or GIGABIT purchase. Only 1 needed per Copier/Printer.	
HCSUIFA	HCS UI Fixed Angle (498K17	820)		N/C
INTEGSFT	Integrated SquareFold Trimm	er (498K1831	0, TLX, 650K31900)	15,000
			let Finisher w/ 2/3 Hole Punch (TKX)	
LEFT-UI	Left UI Kit (497K07290, 497K			85
LUI2TOHCF	Oversize HCF 2T FCW UI Mo		07300)	N/C
MUA	C/Z Folder CSE Required fo			5,700
NBV	Dolly Cart (for use with High ((er) (STACKER)	995
PDFKIT2	PDF Kit (497K09140, 497K09			2,850
SECRWATR	Secure Watermark Kit (497k0			995
STAPLER2	Convenience Stapler (498K08		1.6	299
USBHUB	USB HUB Kit (497K06750) (CSE Required	a for install	150
497K05270	Mobility Plates See below			N/C
		# of Plates		# of Plates
Configuratio	on # of Plates (497K05270)	Required	Configuration # of Plates (497K05270)	Required
D136 C/P or P	rinter	3	Standard Finisher Plus (Partner Finishing Interface Module)	4
2-tray HCF		2	Tape Binder	2
2-tray OHCF		2	CZ Folder	1
			SquareFold Trimmer	1
		2		•
Standard (Star	ole) or Booklet Maker			
Finishers	ble) or Booklet Maker / D125 Printer delivered/installed except where	2 e noted; CSE ro	GBC Advance Punch	1
Finishers Xerox D110 Carrier When o	/ D125 Printer delivered/installed except where ordering a D110 or D125 Printer, 10/D125 orders should be proce	e noted; CSE ro <u>you must</u> also ssed in SPA ar	equired when particular accessories are ordered. o order the Xerox FreeFlow [®] Print Server (FFSRVR) nd routed accordingly.	1
Finishers Xerox D110 Carrier When o The D12	/ D125 Printer delivered/installed except where ordering a D110 or D125 Printer, 10/D125 orders should be proce D110 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K33620), Nationalization	e noted; CSE ro <u>you must</u> also ssed in SPA ar ed Badge (BY 0), MSI Bypas Kit (650K344	equired when particular accessories are ordered. o order the Xerox FreeFlow [®] Print Server (FFSRVR) nd routed accordingly. (2), Initialization Kit (Dongle) (497K14540), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 51).	1
Finishers Xerox D110 Carrier When o The D17 D110PRT	/ D125 Printer delivered/installed except where ordering a D110 or D125 Printer, 10/D125 orders should be proce D110 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K33620), Nationalization This configuration represents mod D125 Printer (BG1) with Spe	e noted; CSE ro <u>you must</u> also ssed in SPA ar ed Badge (BY 0), MSI Bypas Kit (650K3445 ed Badge (BY 0), MSI Bypas Kit (650K3445	equired when particular accessories are ordered. o order the Xerox FreeFlow® Print Server (FFSRVR) ad routed accordingly. 2), Initialization Kit (Dongle) (497K14540), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 51). <i>able version level 08.</i> (4), Initialization Kit (Dongle) (497K14560), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 1).	
Finishers Xerox D110 / • Carrier • When o • The D1' D110PRT D125PRT	/ D125 Printer delivered/installed except where ordering a D110 or D125 Printer, 10/D125 orders should be proce D110 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K33620), Nationalization This configuration represents mod D125 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K3620), Nationalization k	e noted; CSE ro <u>you must</u> also ssed in SPA ar ed Badge (BY 0), MSI Bypas Kit (650K3445 ed Badge (BY 0), MSI Bypas Kit (650K3445	equired when particular accessories are ordered. o order the Xerox FreeFlow® Print Server (FFSRVR) ad routed accordingly. 2), Initialization Kit (Dongle) (497K14540), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 51). <i>able version level 08.</i> (4), Initialization Kit (Dongle) (497K14560), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 1).	
Finishers Xerox D110 / • Carrier • When o • The D1' D110PRT D125PRT You Must Chool	/ D125 Printer delivered/installed except where ordering a D110 or D125 Printer, 10/D125 orders should be proce D110 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K33620), Nationalization This configuration represents mo D125 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K3620), Nationalization k This configuration represents mo ose ONE of the Following:	e noted; CSE ro <u>you must</u> also ssed in SPA ar ed Badge (BY 0), MSI Bypas Kit (650K3445 ed Badge (BY 0), MSI Bypas Kit (650K3445	equired when particular accessories are ordered. o order the Xerox FreeFlow® Print Server (FFSRVR) ad routed accordingly. 2), Initialization Kit (Dongle) (497K14540), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 51). <i>able version level 08.</i> (4), Initialization Kit (Dongle) (497K14560), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 1).	
Finishers Xerox D110 / Carrier When o The D1 D110PRT D125PRT	/ D125 Printer delivered/installed except where ordering a D110 or D125 Printer, 10/D125 orders should be proce D110 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K33620), Nationalization This configuration represents mo D125 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K3620), Nationalization k This configuration represents mo	e noted; CSE re <u>you must</u> also ssed in SPA ar ed Badge (BY 0), MSI Bypas Kit (650K3445 st current shipp ed Badge (BY 0), MSI Bypas (it (650K3445 st current shipp	equired when particular accessories are ordered. o order the Xerox FreeFlow® Print Server (FFSRVR) ad routed accordingly. 2), Initialization Kit (Dongle) (497K14540), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 51). <i>able version level 08.</i> (4), Initialization Kit (Dongle) (497K14560), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 1).	\$65,500
Finishers Xerox D110 / Carrier When o The D1 D110PRT D125PRT D125PRT You Must Choo BYPASS HIGHCAPFD	/ D125 Printer delivered/installed except where ordering a D110 or D125 Printer, 10/D125 orders should be proce D110 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K33620), Nationalization This configuration represents mo D125 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K3620), Nationalization K This configuration represents mo D25 ONE of the Following: Bypass Chute (497K02520) High Capacity Feeder (ACH,	e noted; CSE re you must also ssed in SPA ar ed Badge (BY 0), MSI Bypas Kit (650K3445 st current shipp (0), MSI Bypas (it (650K3445 st current shipp) (it (650K3445) (it (650K3445)	equired when particular accessories are ordered. o order the Xerox FreeFlow® Print Server (FFSRVR) and routed accordingly. 2), Initialization Kit (Dongle) (497K14540), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 51). able version level 08. 4), Initialization Kit (Dongle) (497K14560), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 1). able version level 08.	\$65,500
Finishers Xerox D110 / Carrier When o The D17 D110PRT D125PRT D125PRT D125PRT You Must Choo BYPASS HIGHCAPFD OVRSZHCF	/ D125 Printer delivered/installed except where ordering a D110 or D125 Printer, 10/D125 orders should be proce D110 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K33620), Nationalization This configuration represents mo D125 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K3620), Nationalization k This configuration represents mo Se ONE of the Following: Bypass Chute (497K02520) High Capacity Feeder (ACH, Oversized High Capacity Fee	e noted; CSE re you must also ssed in SPA ar ed Badge (BY 0), MSI Bypas Kit (650K3445 st current shipp ed Badge (BY 0), MSI Bypas (it (650K3445 st current shipp) 498K10700) der (AKC, 498	equired when particular accessories are ordered. o order the Xerox FreeFlow® Print Server (FFSRVR) ad routed accordingly. 2), Initialization Kit (Dongle) (497K14540), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 51). <i>able version level 08.</i> (4), Initialization Kit (Dongle) (497K14560), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 1).	\$65,500 350 2,700
Finishers Xerox D110 / Carrier When o The D12 D110PRT D125PRT D125PRT You Must Choo BYPASS HIGHCAPFD OVRSZHCF OVRSZHF2	/ D125 Printer delivered/installed except where ordering a D110 or D125 Printer, 10/D125 orders should be proce D110 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K33620), Nationalization This configuration represents mod D125 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K3620), Nationalization k This configuration represents mod D25 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K3620), Nationalization k This configuration represents mod D25 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K3620), Nationalization k This configuration represents mod D25 Printer (BG1) (50K3620), Nationalization k This configuration represents mod D25 Printer (BG1) (50K3620), Nationalization k This configuration represents mod D125 Printer (BG1) (50K3620), Nationalization k (50K3620), Nationalization k (50K3620), Nationalization k (50K3620), Nationalization k (50K3620	e noted; CSE re you must also ssed in SPA ar ed Badge (BY 0), MSI Bypas Kit (650K3445 st current shipp ed Badge (BY 0), MSI Bypas (it (650K3445 st current shipp) 498K10700) der (AKC, 498	equired when particular accessories are ordered. o order the Xerox FreeFlow® Print Server (FFSRVR) nd routed accordingly. 2), Initialization Kit (Dongle) (497K14540), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 51). able version level 08. 4), Initialization Kit (Dongle) (497K14560), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 1). able version level 08. 8K15381, 498K18310) . CSE Required for install	\$65,500 350 2,700 4,000
Finishers Xerox D110 / Carrier When o The D17 D110PRT D125PRT You Must Choo BYPASS HIGHCAPFD OVRSZHCF OVRSZHF2 You Must Choo	/ D125 Printer delivered/installed except where ordering a D110 or D125 Printer, 10/D125 orders should be proce D110 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K33620), Nationalization This configuration represents mod D125 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K3620), Nationalization k This configuration represents mod pse ONE of the Following: Bypass Chute (497K02520) High Capacity Feeder (ACH, Oversized High Capacity Fee 2 Tray Oversize High Capacit	e noted; CSE re you must also ssed in SPA ar ed Badge (BY 0), MSI Bypas Kit (650K3445 ed Badge (BY 0), MSI Bypas (it (650K3445 st current shipp) (it (650K3445) (it (650K3445)) (it (650K3445) (it (650K3445)) (it (650K345)) (it (650K35)) (it (650K35)) (it (650K35)) (it (650	equired when particular accessories are ordered. o order the Xerox FreeFlow® Print Server (FFSRVR) ad routed accordingly. 2), Initialization Kit (Dongle) (497K14540), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 51). <i>able version level 08.</i> 4), Initialization Kit (Dongle) (497K14560), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 1). <i>able version level 08.</i> 8K15381, 498K18310) . CSE Required for install 3, 498K18310) - Carrier Install	\$65,500 350 2,700 4,000 6,500
Finishers Xerox D110 / Carrier When o The D17 D110PRT D125PRT You Must Choo BYPASS HIGHCAPFD OVRSZHCF OVRSZHF2 You Must Choo	/ D125 Printer delivered/installed except where ordering a D110 or D125 Printer, 10/D125 orders should be proce D110 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K33620), Nationalization <i>This configuration represents mo</i> D125 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K3620), Nationalization k <i>This configuration represents mo</i> D56 ONE of the Following: Bypass Chute (497K02520) High Capacity Feeder (ACH, Oversized High Capacity Fee 2 Tray Oversize High Capacit D56 ONE of the Following: Restricted Access Install (NAt	e noted; CSE re you must also ssed in SPA ar ed Badge (BY 0), MSI Bypas Kit (650K3445 st current shipp ed Badge (BY 0), MSI Bypas Kit (650K3445 st current shipp 498K10700) der (AKC, 498 y Feeder (B98 8) (Required 1	equired when particular accessories are ordered. o order the Xerox FreeFlow® Print Server (FFSRVR) ad routed accordingly. 2), Initialization Kit (Dongle) (497K14540), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 51). <i>able version level 08.</i> 4), Initialization Kit (Dongle) (497K14560), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 1). <i>able version level 08.</i> 8K15381, 498K18310) . CSE Required for install 3, 498K18310) - Carrier Install for customers with security requirements that do not allow	\$65,500 350 2,700 4,000
Finishers Xerox D110 / • Carrier • When o • The D17 D110PRT D125PRT D125PRT D125PRT D125PRT D125PRT D125PRT D125PRT OVRSZHCF OVRSZHCF OVRSZHCF OVRSZHCF OVRSZHCF OVRSZHCF	/ D125 Printer delivered/installed except where ordering a D110 or D125 Printer, 10/D125 orders should be proce D110 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K33620), Nationalization <i>This configuration represents mo</i> D125 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K3620), Nationalization k <i>This configuration represents mo</i> D56 ONE of the Following: Bypass Chute (497K02520) High Capacity Feeder (ACH, Oversized High Capacity Fee 2 Tray Oversize High Capacit D56 ONE of the Following: Restricted Access Install (NAt the use of flash media [dom	e noted; CSE re you must also ssed in SPA ar ed Badge (BY 0), MSI Bypas Kit (650K3445 st current shipp ed Badge (BY 0), MSI Bypas Kit (650K3445 st current shipp 498K10700) der (AKC, 498 y Feeder (B98 8) (Required 1	equired when particular accessories are ordered. o order the Xerox FreeFlow® Print Server (FFSRVR) ad routed accordingly. 2), Initialization Kit (Dongle) (497K14540), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 51). <i>able version level 08.</i> 4), Initialization Kit (Dongle) (497K14560), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 1). <i>able version level 08.</i> 8K15381, 498K18310) . CSE Required for install 3, 498K18310) - Carrier Install for customers with security requirements that do not allow	\$65,500 350 2,700 4,000 6,500 120
Finishers Xerox D110 / Carrier When o The D17 D110PRT D125PRT D125PRT D125PRT D125PRT D125PRT D125PRT D125PRT OVRSZHCF OVRSZHCF OVRSZHCF OVRSZHCF OVRSZHCF OVRSZHCF OVRSZHCF	/ D125 Printer delivered/installed except where ordering a D110 or D125 Printer, 10/D125 orders should be proce D110 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K33620), Nationalization <i>This configuration represents mo</i> D125 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K3620), Nationalization k <i>This configuration represents mo</i> D25 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K3620), Nationalization k <i>This configuration represents mo</i> D25 ONE of the Following: Bypass Chute (497K02520) High Capacity Feeder (ACH, - Oversized High Capacity Fee 2 Tray Oversize High Capacit D56 ONE of the Following: Restricted Access Install (NAt the use of flash media [dom Standard Install (497K10900)	e noted; CSE re you must also ssed in SPA ar ed Badge (BY 0), MSI Bypas Kit (650K3445 st current shippa (it (650K3445) st current shippa (it (650K345)) st current shippa (it (650K345)) st current shippa (it (650K345)) st current shipp	equired when particular accessories are ordered. o order the Xerox FreeFlow® Print Server (FFSRVR) ad routed accordingly. 2), Initialization Kit (Dongle) (497K14540), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 51). <i>able version level 08.</i> 4), Initialization Kit (Dongle) (497K14560), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 1). <i>able version level 08.</i> 8K15381, 498K18310) . CSE Required for install 3, 498K18310) - Carrier Install for customers with security requirements that do not allow	\$65,500 350 2,700 4,000 6,500
Finishers Xerox D110 / Carrier When o The D1 D110PRT D125PRT D125PRT D125PRT D125PRT OVRSZHCF OVRSZHCF OVRSZHCF OVRSZHF2 You Must Choo INSTSECUR	/ D125 Printer delivered/installed except where ordering a D110 or D125 Printer, 10/D125 orders should be proce D110 Printer (BG1) with Spe- UI Right Mount Kit (497K0911 (650K33620), Nationalization This configuration represents mo- D125 Printer (BG1) with Spe- UI Right Mount Kit (497K0911 (650K3620), Nationalization K This configuration represents mo- D25 Printer (BG1) with Spe- UI Right Mount Kit (497K0911 (650K3620), Nationalization K This configuration represents mo- D25 ONE of the Following: Bypass Chute (497K02520) High Capacity Feeder (ACH, Oversized High Capacity Fee 2 Tray Oversize High Capacit D25 ONE of the Following: Restricted Access Install (NA the use of flash media [dom Standard Install (497K10900) D25 AT LEAST ONE of the Following	e noted; CSE m you must also ssed in SPA ar ed Badge (BY 0), MSI Bypas Kit (650K3445 st current shippe ed Badge (BY 0), MSI Bypas (it (650K3445 st current shippe 498K10700) der (AKC, 498 y Feeder (B98 8) (Required to gle] onsite- e	equired when particular accessories are ordered. o order the Xerox FreeFlow® Print Server (FFSRVR) ad routed accordingly. 2), Initialization Kit (Dongle) (497K14540), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 51). <i>able version level 08.</i> 4), Initialization Kit (Dongle) (497K14560), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 1). <i>able version level 08.</i> 8K15381, 498K18310) . CSE Required for install 3, 498K18310) - Carrier Install for customers with security requirements that do not allow	\$65,500 350 2,700 4,000 6,500 120 N/C
Finishers Xerox D110 / Carrier When o The D17 D110PRT D110PRT D125PRT D125PRT D125PRT OVRSZHCF OVRSZHCF OVRSZHCF OVRSZHF2 You Must Choo INSTSECUR INSTSTD You Must Choo	/ D125 Printer delivered/installed except where ordering a D110 or D125 Printer, 10/D125 orders should be proce D110 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K33620), Nationalization This configuration represents mo D125 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K3620), Nationalization K This configuration represents mo D25 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K3620), Nationalization K This configuration represents mo D25 ONE of the Following: Bypass Chute (497K02520) High Capacity Feeder (ACH, Oversized High Capacity Fee 2 Tray Oversize High Capacit D25 ONE of the Following: Restricted Access Install (NAX the use of flash media [dom Standard Install (497K10900) D25 AT LEAST ONE of the Fo Interface Module (MAX, 498K	e noted; CSE re you must also ssed in SPA ar ed Badge (BY 0), MSI Bypas Kit (650K3445 st current shippe ed Badge (BY 0), MSI Bypas (it (650K3445 st current shippe 498K10700) der (AKC, 498 y Feeder (B98 8) (Required f gle] onsite- e Ilowing: 18310)	equired when particular accessories are ordered. o order the Xerox FreeFlow® Print Server (FFSRVR) ad routed accordingly. 2), Initialization Kit (Dongle) (497K14540), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 51). <i>able version level 08.</i> 4), Initialization Kit (Dongle) (497K14560), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 1). <i>able version level 08.</i> 8K15381, 498K18310) . CSE Required for install 3, 498K18310) - Carrier Install for customers with security requirements that do not allow	\$65,500 350 2,700 4,000 6,500 120
Finishers Xerox D110 / Carrier When o The D1 ⁷ D110PRT D110PRT D125PRT D125PRT D125PRT D125PRT OVRSZHCF OVRSZHCF OVRSZHCF OVRSZHCF OVRSZHF2 You Must Choo INSTSECUR INSTSTD You Must Choo INTERFACE	/ D125 Printer delivered/installed except where ordering a D110 or D125 Printer, 10/D125 orders should be proce D110 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K33620), Nationalization This configuration represents mo D125 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K3620), Nationalization K This configuration represents mo D25 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K3620), Nationalization K This configuration represents mo D25 ONE of the Following: Bypass Chute (497K02520) High Capacity Feeder (ACH, Oversized High Capacity Fee 2 Tray Oversize High Capacit D25 ONE of the Following: Restricted Access Install (NAX the use of flash media [dom Standard Install (497K10900) D26 AT LEAST ONE of the Fo Interface Module (MAX, 498K ocannot be purchase notations below	e noted; CSE re you must also ssed in SPA ar ed Badge (BY 0), MSI Bypas Kit (650K3445 st current shipped Badge (BY 0), MSI Bypas (it (650K3445 st current shipped (it (650K3445) st current shipped (it (650K345) st current shipped (it (650K345) s	equired when particular accessories are ordered. order the Xerox FreeFlow® Print Server (FFSRVR) ad routed accordingly. 2), Initialization Kit (Dongle) (497K14540), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 51). <i>able version level 08</i> . 4), Initialization Kit (Dongle) (497K14560), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 1). <i>able version level 08</i> . 8K15381, 498K18310) . CSE Required for install 3, 498K18310) - Carrier Install for customers with security requirements that do not allow .g. GSA)	\$65,500 2,700 4,000 6,500 120 N/C
Finishers Xerox D110 / Carrier When o The D1 ⁷ D110PRT D110PRT D125PRT D125PRT D125PRT O125PRT OVRSZHCF OVRSZHCF OVRSZHCF OVRSZHF2 You Must Choc INSTSECUR INSTSECUR INSTSTD You Must Choc INTERFACE MLA	/ D125 Printer delivered/installed except where ordering a D110 or D125 Printer, 10/D125 orders should be proce D110 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K33620), Nationalization This configuration represents mo D125 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K3620), Nationalization K This configuration represents mo D25 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K3620), Nationalization K This configuration represents mo D25 ONE of the Following: Bypass Chute (497K02520) High Capacity Feeder (ACH, Oversized High Capacity Fee 2 Tray Oversize High Capacit D55 ONE of the Following: Restricted Access Install (NAX the use of flash media [dom Standard Install (497K10900) D56 AT LEAST ONE of the Fo Interface Module (MAX, 498K ocannot be purchase notations below	e noted; CSE re you must also ssed in SPA ar ed Badge (BY 0), MSI Bypas Kit (650K3445 st current shippe ed Badge (BY 0), MSI Bypas (it (650K3445 st current shippe 498K10700) der (AKC, 498 y Feeder (B98 8) (Required f gle] onsite- e llowing: 18310) ed as a stand th 2/3 Hole Pu	equired when particular accessories are ordered. order the Xerox FreeFlow® Print Server (FFSRVR) ad routed accordingly. 2), Initialization Kit (Dongle) (497K14540), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 51). <i>able version level 08.</i> 4), Initialization Kit (Dongle) (497K14560), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 1). <i>able version level 08.</i> 8K15381, 498K18310) . CSE Required for install 3, 498K18310) - Carrier Install for customers with security requirements that do not allow .g. GSA)	2,700 4,000 6,500 120 N/C 2,000 6,550
Finishers Xerox D110 / Carrier When o The D1 ⁷ D110PRT D125PRT D125PRT D125PRT O125PRT O125PRT OVRSZHCF OVRSZHCF OVRSZHCF OVRSZHCF OVRSZHF2 You Must Choo INSTSECUR INSTSTD You Must Choo INTERFACE	/ D125 Printer delivered/installed except where ordering a D110 or D125 Printer, 10/D125 orders should be proce D110 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K33620), Nationalization This configuration represents mo D125 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K3620), Nationalization K This configuration represents mo D25 Printer (BG1) with Spe UI Right Mount Kit (497K0911 (650K3620), Nationalization K This configuration represents mo D25 ONE of the Following: Bypass Chute (497K02520) High Capacity Feeder (ACH, Oversized High Capacity Fee 2 Tray Oversize High Capacit D55 ONE of the Following: Restricted Access Install (NAX the use of flash media [dom Standard Install (497K10900) D56 AT LEAST ONE of the Fo Interface Module (MAX, 498K ocannot be purchase notations below	e noted; CSE re you must also ssed in SPA ar ed Badge (BY 0), MSI Bypas Kit (650K3445 st current shippe ed Badge (BY 0), MSI Bypas (it (650K3445 st current shippe 498K10700) der (AKC, 498 y Feeder (B98 8) (Required f gle] onsite- e llowing: 18310) ed as a stand th 2/3 Hole Pu	equired when particular accessories are ordered. order the Xerox FreeFlow® Print Server (FFSRVR) ad routed accordingly. 2), Initialization Kit (Dongle) (497K14540), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 51). <i>able version level 08</i> . 4), Initialization Kit (Dongle) (497K14560), FCW UI PRT (BG4), ss Tray (497K09130), Customer Documentation & Software Kit 1). <i>able version level 08</i> . 8K15381, 498K18310) . CSE Required for install 3, 498K18310) - Carrier Install for customers with security requirements that do not allow .g. GSA)	\$65,500 350 2,700 4,000 6,500 120 N/C 2,000



Market Code/ Product Code	Product Description	Purchase Price \$					
STDFINPLS	 Standard Finisher Plus (Partner Interface Finishing Module) (XMH, XBR, 497K12770, 498K18310, 497K06850) Requires Interface Module (INTERFACE) accessory Required when purchasing Tape Binder (TAPE-BIND) or TXC's eBinder or TXC's RCT Pro30. If purchasing both TAPE-BIND and TXC's Pro 30 for a 'chained' finishing solution, only ONE STDFINPLS is needed in total. CSE Required for install 						
TAPE-BIND	Tape Binder (HWX, 650K30110) Requires Partner Finishing Interface Module (STDFINPLS) accessory 	15,000					
	CSE Required for install	44.000					
rkx	Booklet Finisher w/ 2/3 Hole Punch	11,800					
	se ANY of the Following:	12,400					
ADV-PUNCH	 GBC Advanced Punch (498K18950, UAD, 497N00216) Requires Interface Module (INTERFACE) accessory Also requires purchase of either a Staple Finisher w/ 2/3 Hole Punch (MLA) or Booklet Finisher w/ 2/3 Hole Punch (TKX) or High Capacity Stacker (STACKER) 						
FIDEVICE2	Foreign Interface Device (498K14141) CSE Required for install	150					
ICSUIFA	HCS UI Fixed Angle (498K17820)	N/C					
NTEGSFT	Integrated SquareFold Trimmer (498K18310, TLX, 650K31900) only available for use with Booklet Finisher w/ 2/3 Hole Punch (TKX)						
_EFT-UI	Left UI Kit (497K07290, 497K09120)	85					
UI2TOHCF	Oversize HCF 2T FCW UI Mount Kit (497K07300)	N/C					
IUA	C/Z Folder CSE Required for install	5,700					
IBV	Dolly Cart (for use with High Capacity Stacker) (STACKER)	995					
STAPLER2 97K05270	Convenience Stapler (498K08250) Mobility Plate See below	299 N/C					
	Equipment ComponentIFMGBCHCSD4 finsiher# Plates11212Equipment ComponentD5Square FolderTape						
	FinisherTrimmerPFIMBinder# Plates2122						
Availab	t Server, powered by Fiery le for use with <u>D95CP mainframe only</u> . 95 is Carrier delivered/installed except where noted; CSE required when particular accessories are ordered.						
EFISVR95	Xerox EX Print Server, powered by Fiery (XR1) w/ DFE VSEL Kit (497K09910) & ESD Protection Kit (497K10920).	11,000					
ou May Choos	se ANY of the Following:						
FI-IMAGE	Image Viewer for Black & White (497N01577)	2,800					
FICMPOSE	SeQuence Compose Kit (301N55450)	4,000					
FISEQSTE	SeQuence Suite (YYB)	6,500					
FISEQIMP	SeQuence Impose Kit (301N55460) CSE Required for install	2,550					
FIFACI	FACI (Fiery Advanced Controller Interface Option) Kit (497N01325)	1,995					
NETHUB	Ethernet Hub Option (497N01224) CSE Required for install	495					
XPRHD	Hard Disk Drive Security Option Kit (CAM) CSE Required for install	1,995					
ACISTND	FACI Furniture Option Kit (BVR)	649					
IWT	FreeFlow VI Designer Pro SW & License Kit CSE Required for install	3,495					
/IGROUPA	FreeFlow VI Design Compose SW & License Kit (NWR). CSE Required for install	5,000					
(SISED9B	XSIS Removable Hard Drive – Extra Drive Set (497K10220)	1,500					
XSISRH9B	XSIS Removable Hard Drive – Install Kit (497K10220)	1					



Market Code/ Product Code	Product Description	Purchase Price \$
	t Server, powered by Fiery	
Availab	le for use with <u>D110CP and D125CP mainframes only</u> . It is Carrier delivered/installed except where noted; CSE required when particular accessories are ordered.	
EFISVR	Xerox EX Print Server, powered by Fiery (EX5) w/ DFE VSEL Kit (497K09910) & ESD Protection Kit (497K10920).	12,000
You May Choos	se ANY of the Following:	
EFI-IMAGE	Image Viewer for Black & White (497N01577)	2,800
EFICMPOSE	SeQuence Compose Kit (301N55450)	4,000
EFISEQSTE	SeQuence Suite (YYB)	6,500
EFISEQIMP	SeQuence Impose Kit (301N55460) CSE Required for install	2,550
EXPRHD	Hard Disk Drive Security Option Kit (CAM) CSE Required for install	1,995
EFIFACI	FACI (Fiery Advanced Controller Interface Option) Kit (497N01325)	1,995
ENETHUB	Ethernet Hub Option (497N01224) CSE Required for install	495
FACISTND	FACI Furniture Option Kit (BVR)	649
NWT	FreeFlow VI Designer Pro SW & License Kit. Available only on the Copier/Printer mainframes	3,495
	CSE Required for install	0,400
VIGROUPA	FreeFlow VI Design Compose SW & License Kit (NWR). Available only on the Copier/Printer mainframes	5,000
VIGROUPA		5,000
	CSE Required for install	0.000
XSISRH9B	XSIS Removable Hard Drive – Install Kit (497K10210)	3,000
XSISED9B	XSIS Removable Hard Drive – Extra Drive Kit (497K10220)	1,500
	t Server, powered by Fiery	
	le for use with D136CP mainframe only.	
EFISVR	t is Carrier delivered/installed except where noted; CSE required when particular accessories are ordered.	
EFISVR136	Xerox EX Print Server, powered by Fiery (A5Y)	12,000
ou May Choos	se ANY of the Following:	
EFICOMPOS	Compose Kit (497N02109)	4,000
EFIIMPOS	Impose Kit (497N02214) CSE Required for install	2,550
EXPRHD	Hard Disk Drive Security Option Kit (CAM) CSE Required for install	1,995
EFIFACI	FACI (Fiery Advanced Controller Interface Option) Kit (497N01325)	1,995
ENETHUB	Ethernet Hub Option (497N01224) CSE Required for install	495
EFIMG136	ImageViewer for B&W (497N02659)	2,800
	FACI Furniture Option Kit (BVR)	649 6,500
	Mono Calibration (497N02931) CSE Required for install	,
NWT	FreeFlow VI Designer Pro SW & License Kit. Available only on the Copier/Printer mainframe CSE Required for install 	3,495
VIGROUPA	FreeFlow VI Design Compose SW & License Kit (NWR). Available only on the Copier/Printer mainframe CSE Required for install 	5,000
	ow [®] Print Server	
	le on D95CP, D110CP, D125CP, D110PRT, D125PRT	
	Ist order a FFSRVR when ordering a D110PRT or D125PRT mainframe mainframe and ALL accessories are Carrier deliverable and CSE Installable for new business and post sale transaction	ione
FFSRVR	Xerox FreeFlow [®] Print Server (LOA) with 19" Color Monitor (8RX), US Power Strip Kit (498K16920), FFPS	18,500
	Nationalization Kit (650K30060), Operating System License (BRL), and FF9.0 SP3 Software &	
	Documentation Kit (301K31900). This configuration represents most current shippable version level 01.	
	ose ONE of the Following:	
CP95NBL	D95 CP Server License (PB6) Must also order VSELFFPS accessory	N/C
CP110NBL	D110 CP Server License (RX7) Must also order VSELFFPS accessory	N/C
	D125 CP Server License (PB9) Must also order VSELFFPS accessory	N/C
CP125NBL	D110 Printer Server License (RX8)	N/C
		NI/O
P110NBL	D125 Printer Server License (PX0)	N/C
P110NBL P125NBL		N/C
P110NBL P125NBL You May Choos	se ANY of the Following:	
B5L	se ANY of the Following: Controller Stand	250
P110NBL P125NBL You May Choos B5L IPDSW1	se ANY of the Following: Controller Stand IPDS Software License (YHP)	250 10,000
P110NBL P125NBL You May Choo s	se ANY of the Following: Controller Stand	250



Market Code/ Product Code	Product Description	Purchase Price \$
VSELFFPS	VSEL Kit required for CP configurations (497K09910).	N/C
	MUST be ordered with a D95CP (CP95NBL), D110CP (CP110NBL) or D125CP (CP125NBL)	
	Should never be ordered with a D110PRT (P110NBL) or D125PRT (P125NBL)	
XSISRH4G	XSIS Removable Hard Drive – Install Kit (497K11561)	6,000
XSISED4G	XSIS Removable Hard Drive – Extra Drive Kit (497K11550)	1,900
Xerox FreeFlo	ow [®] Print Server	
	le on the D136CP and D136PRT	
	ist order a FFSRVR136 when ordering a D136PRT mainframe	
FFSVR [®]	136 mainframe and ALL accessories are Carrier deliverable and CSE Installable for new business and post sale tran	sactions
FFSRVR136	Xerox Freeflow Print Server (G6X), 19" Color Monitor (8RX), Power Strip (498K16920), Nationalization Kit (650K30060), Software License (BRL), Free Flow 9.0 SP3 Software and Documentation Kit (301K31910). <i>This configuration represents most current shippable version level 01.</i>	18,500
You Must Choo	ose ONE of the Following:	
CP136NBL	D136 C/P Server License (B2D)	N/C
P136NBL	D136 Printer Server License (B3D)	N/C
You May Choos	se ANY of the Following:	
B5L	Controller Stand	250
IPDSW1	IPDS Software License (YHP)	10,000
LCDSSW	LCDS Software License (NCU, 301K11443)	10,000
NWT	FreeFlow VI Designer Pro SW & License Kit	3,495
VIGROUPA	FreeFlow VI Design Compose SW & License Kit (NWR)	5.000



0111) 11000 0		nance charge are indicated ir	1				<u>.</u>
Market / Product Code	Component Description (All Configurations Unless Noted)	Service Plan Name	Maintenance Bill Code / Meter Ind	Lease Bill Code / Meter Ind	Monthly Base Charge \$	Monthly Print Allowance	Charge Per Print
Xerox D95 / D	0110 / D125 / D136 Copi	er/Printers & Printers					
D95CP	D95 Copier/Printer	Full Service Maint. Plan	X9E1/1	XG81-7/1	0	-	.0044
		Full Service Maint. Plan	X961/1	XG61-7/1	175	-	.0023
		Full Service Maint. Plan	X971/1	XG71-7/1	330	100,000	.0020
D110CP	D110 Copier/Printer	Full Service Maint. Plan	X941/1	X2T1-7/1	0	-	.0044
D110PRT	D110 Printer	Full Service Maint. Plan	X961/1	X3T1-7/1	175	-	.0023
D125CP	D125 Copier/Printer	Full Service Maint. Plan	X971/1	XG71-7/1	330	100,000	.0020
D125PRT	D125 Printer	Full Service Maint. Plan	X981/1	XG81-7/1	390	200,000	.0017
D136CP	D136 Copier/Printer	Full Service Maint, Plan	X9L1/1	XG31-7/1	0	-	.0044
515001		Full Service Maint. Plan	X9I1/1	X4T1-7/1	175		.0023
		Full Service Maint. Plan	X9H1/1	XG41-7/1	330	100,000	.0020
		Full Service Maint. Plan	X9W1/1	X3H1-7/1			
					390	200,000	.0017
	GBC [®] AdvancedPunch [™]		-	-	65	-	-
NTEGSFT	Integrated SquareFold® T		-	-	50	-	-
	Oversized High Capacity		-	-	60	-	-
OVRSZHCF2 OVRSZHF2	2 Tray Oversize High Cap	-	-	-	75	-	-
SA1-MAG2	2 Tray Oversize High Cap Magstripe Reader USB Ve	•	-	-	75 7	-	-
SA1-MIF2	Mifare/Hid I-Class USB V		-	-	8	-	-
SA1-HID2	Hid Reader (USB Version		-	-	8	-	-
SA-HID125	Secure Access SW w/ HI		-	-	11	-	-
SA-MAGSTR	Secure Access SW w/ In		-	-	10	-	-
SA-MIFARE	Secure Access SW with N			-	10		
STDFINPLS	Standard Finisher Plus			-	50		
TAPE-BIND	Tape Binder		-	-	125	-	-
XSISRH9B	XSIS Removable Hard Dr	ive – Install Kit		-	30		
XSISED9B	XSIS Removable hard Dri		-	-	15	_	
	ver for D95 / D110 / D125		· & Printers		10	<u> </u>	
	Xerox EX Print Server	Full Service Maint. Plan	X981/0	(¥100/0)	50		
EFISVR	powered by Fiery®	Fuil Service Maint. Plan	A901/U	(X199/0)	50	-	-
EFISVR95							
EFISVR136	FreeFlow [®] VI Design Pro				40	_	
	•		-	-	-	-	-
/IGROUPA KSISRH9B	FreeFlow [®] VI Compose XSIS Removable Hard Dr	ive – Install Kit	-	-	60	-	-
KSISED9B	XSIS Removable hard Dr		-	-	30 15	-	-
	ow [®] Print Server D95 /		- nior/Printor	- Printor	15	-	-
FFSRVR	Freeflow [®] Print Server	Full Service Maint. Plan	X981/0	(x199/0)	50	-	-
FFSRVR136	D95/110/125 Freeflow [®] Print Server D136	Full Service Maint. Plan	X981/0	(x199/0)	50	-	-



Equipment Sale & Maintenance

Price List reflects both Commercial and State/Local marketing segments

Equipment Maintenance Pricing

Only those ac	cessories that carry a mainter	nance charge are indicated in	the Maintenance	Drico List			
	Component Description (All Configurations Unless Noted)		Maintenance Bill Code / Meter Ind	Lease Bill Code / Meter Ind	Monthly Base Charge \$	Monthly Print Allowance	Charge Per Print
LCDSSW	LCDS License		-	-	125	-	-
IPDSW1	IPDS SW License		-	-	125	-	-
NWT	FreeFlow [®] VI Design Pro		-	-	40	-	-
VIGROUPA	FreeFlow [®] VI Compose		-	-	60	-	-
XSISRH4G	XSIS Removable Hard Dr	ive – Install Kit	-	-	60	-	-
XSISED4G	XSIS Removable hard Dri	ve – Extra Drive Kit	-	-	30	-	-
	aking Equipment: M opier & Copier/Printer				onversion	S.	
	4595 Copier	Full Service Maint. Plan	X9L1/1	XG31-7/1	75	-	.0105
	4595 Copier/Printer	Full Service Maint. Plan	X9C1/1	X201-7/1	298	-	.0059
		Full Service Maint. Plan	X9H1/1	X3H1-7/1	793	125,000	.0062
OVRSZHCF	Oversized High Capacity	Feeder	-	-	60	-	
	aniar 9 Canier/Drinter						
	opier & Copier/Printer	Full Service Maint. Plan		•	100	_	0450
	4110 Copier/Copier	Full Service Maint. Plan	X9L1/1	XG31-7/1	109		.0152
P/4110CP	Printer		X9C1/1	X201-7/1	435	-	.0085
		Full Service Maint. Plan	X9H1/1	X3H1-7/1	1,154	125,000	.0086
		Full Service Maint. Plan	X9U1/1	X1G1-7/1	1,674	200,000	.0065
		CPC Only 1YR FSMA	X9G1/1	X1A1-7/1	1,892	200,000	.0045
VIGROUPA	FreeFlow [®] VI Compose		-	-	60	-	-
NWT	FreeFlow [®] VI Design Pro		-	-	40	-	-
	terprise Printing Syste	em (Market codes: 4112EP	S, P4112EPS / 4	127EPS, P4127	7EPS)		
P/4112EPS	4112/4127 EPS	Full Service Maint. Plan	X9L1/1	XG31-7/1	75	-	.0105
	4112/4127 EPS	Full Service Maint. Plan	X9C1/1	X201-7/1	298	-	.0105 .0059
	4112/4127 EPS	Full Service Maint. Plan Full Service Maint. Plan	X9C1/1 X9H1/1	X201-7/1 X3H1-7/1	-	- - 125,000	
	4112/4127 EPS	Full Service Maint. Plan Full Service Maint. Plan Full Service Maint. Plan	X9C1/1 X9H1/1 X9U1/1	X201-7/1	298 793 1,150	- 125,000 200,000	.0059 .0062 .0045
	4112/4127 EPS	Full Service Maint. Plan Full Service Maint. Plan	X9C1/1 X9H1/1	X201-7/1 X3H1-7/1	298 793	- 125,000	.0059 .0062
P/4127EPS	4112/4127 EPS GBC [®] AdvancedPunch [™]	Full Service Maint. Plan Full Service Maint. Plan Full Service Maint. Plan CPC Only 1YR FSMA	X9C1/1 X9H1/1 X9U1/1	X201-7/1 X3H1-7/1 X1G1-7/1	298 793 1,150	- 125,000 200,000	.0059 .0062 .0045
P/4127EPS ADVPUNCH		Full Service Maint. Plan Full Service Maint. Plan Full Service Maint. Plan CPC Only 1YR FSMA	X9C1/1 X9H1/1 X9U1/1	X201-7/1 X3H1-7/1 X1G1-7/1 X1A1-7/1	298 793 1,150 1,300	- 125,000 200,000	.0059 .0062 .0045
P/4127EPS ADVPUNCH INTEGSFT	GBC [®] AdvancedPunch [™]	Full Service Maint. Plan Full Service Maint. Plan Full Service Maint. Plan CPC Only 1YR FSMA	X9C1/1 X9H1/1 X9U1/1	X201-7/1 X3H1-7/1 X1G1-7/1 X1A1-7/1	298 793 1,150 1,300 65	- 125,000 200,000	.0059 .0062 .0045
P/4127EPS ADVPUNCH INTEGSFT OVRSZHCF OVRSZHCF2	GBC [®] AdvancedPunch [™] Integrated SquareFold®	Full Service Maint. Plan Full Service Maint. Plan Full Service Maint. Plan CPC Only 1YR FSMA Trimmer Module	X9C1/1 X9H1/1 X9U1/1 X9G1/1 - -	X201-7/1 X3H1-7/1 X1G1-7/1 X1A1-7/1 - -	298 793 1,150 1,300 65 50	- 125,000 200,000 200,000 - -	.0059 .0062 .0045 .0029 - -
P/4127EPS ADVPUNCH INTEGSFT OVRSZHCF OVRSZHCF2 SA-HID125	GBC [®] AdvancedPunch [™] Integrated SquareFold® Oversized High Capacity	Full Service Maint. Plan Full Service Maint. Plan Full Service Maint. Plan CPC Only 1YR FSMA Trimmer Module Feeder pacity Feeder	X9C1/1 X9H1/1 X9U1/1 X9G1/1 - - -	X201-7/1 X3H1-7/1 X1G1-7/1 X1A1-7/1 - - -	298 793 1,150 1,300 65 50 60	- 125,000 200,000 200,000 - - - -	.0059 .0062 .0045 .0029 - -
ADVPUNCH INTEGSFT OVRSZHCF OVRSZHCF2 SA-HID125 SA-MAGSTR	GBC [®] AdvancedPunch [™] Integrated SquareFold® Oversized High Capacity 2 Tray Oversize High Ca	Full Service Maint. Plan Full Service Maint. Plan Full Service Maint. Plan CPC Only 1YR FSMA Trimmer Module Feeder pacity Feeder HID 125kHz Reader	X9C1/1 X9H1/1 X9U1/1 X9G1/1 - - -	X201-7/1 X3H1-7/1 X1G1-7/1 X1A1-7/1 - - -	298 793 1,150 1,300 65 50 60 75	- 125,000 200,000 200,000 - - - -	.0059 .0062 .0045 .0029 - -
P/4127EPS ADVPUNCH INTEGSFT OVRSZHCF OVRSZHCF2 SA-HID125 SA-HID125 SA-MAGSTR SA-MIFARE	GBC [®] AdvancedPunch [™] Integrated SquareFold® Oversized High Capacity 2 Tray Oversize High Ca Secure Access SW with	Full Service Maint. Plan Full Service Maint. Plan Full Service Maint. Plan CPC Only 1YR FSMA Trimmer Module Feeder pacity Feeder HID 125kHz Reader Magstripe Reader	X9C1/1 X9H1/1 X9U1/1 X9G1/1 - - -	X201-7/1 X3H1-7/1 X1G1-7/1 X1A1-7/1 - - -	298 793 1,150 1,300 65 50 60 75 11	- 125,000 200,000 200,000 - - - -	.0059 .0062 .0045 .0029 - -
P/4127EPS ADVPUNCH INTEGSFT OVRSZHCF OVRSZHCF2 SA-HID125 SA-MAGSTR SA-MIFARE SQFOLDTRM	GBC [®] AdvancedPunch [™] Integrated SquareFold® Oversized High Capacity 2 Tray Oversize High Ca Secure Access SW with Secure Access SW with Secure Access SW with SquareFold® Trimmer M	Full Service Maint. Plan Full Service Maint. Plan Full Service Maint. Plan CPC Only 1YR FSMA Trimmer Module Feeder pacity Feeder HID 125kHz Reader Magstripe Reader MiFare Reader odule	X9C1/1 X9H1/1 X9U1/1 X9G1/1 - - - - - - - - -	X201-7/1 X3H1-7/1 X1G1-7/1 X1A1-7/1 - - - - - - - - - - - - - - - -	298 793 1,150 1,300 65 50 60 75 11 10	- 125,000 200,000 - - - - - - - - - -	.0059 .0062 .0045 .0029 - - - - - - - - - -
P/4127EPS ADVPUNCH INTEGSFT OVRSZHCF OVRSZHCF2 SA-HID125 SA-HID125 SA-MAGSTR SA-MIFARE SQFOLDTRM XSISRH4C	GBC [®] AdvancedPunch [™] Integrated SquareFold® Oversized High Capacity 2 Tray Oversize High Ca Secure Access SW with Secure Access SW with Secure Access SW with SquareFold® Trimmer M XSIS Removable Hard Dr	Full Service Maint. Plan Full Service Maint. Plan Full Service Maint. Plan CPC Only 1YR FSMA Trimmer Module Feeder pacity Feeder HID 125kHz Reader Magstripe Reader MiFare Reader lodule ive – Install Kit	X9C1/1 X9H1/1 X9U1/1 X9G1/1 - - - - - - - - - - - - - - -	X201-7/1 X3H1-7/1 X1G1-7/1 X1A1-7/1 - - - - - - - - - - - - - - - - - - -	298 793 1,150 1,300 65 50 60 75 11 10 11	- 125,000 200,000 - - - - - - - - - - - -	.0059 .0062 .0045 .0029 - - - - - - - - - -
P/4127EPS ADVPUNCH INTEGSFT OVRSZHCF OVRSZHCF2 SA-HID125 SA-MAGSTR SA-MIFARE SQFOLDTRM XSISRH4C	GBC [®] AdvancedPunch [™] Integrated SquareFold® Oversized High Capacity 2 Tray Oversize High Ca Secure Access SW with Secure Access SW with Secure Access SW with SquareFold® Trimmer M	Full Service Maint. Plan Full Service Maint. Plan Full Service Maint. Plan CPC Only 1YR FSMA Trimmer Module Feeder pacity Feeder HID 125kHz Reader Magstripe Reader MiFare Reader lodule ive – Install Kit	X9C1/1 X9H1/1 X9U1/1 X9G1/1 - - - - - - - - - - - - - - -	X201-7/1 X3H1-7/1 X1G1-7/1 X1A1-7/1 - - - - - - - - - - - - - - - - - - -	298 793 1,150 1,300 65 50 60 75 11 10 11 50	- 125,000 200,000 - - - - - - - - - - - -	.0059 .0062 .0045 .0029 - - - - - - - - - -
P/4127EPS ADVPUNCH INTEGSFT OVRSZHCF2 SA-HID125 SA-HID125 SA-MIFARE SQFOLDTRM XSISRH4C XSISED4C 4112 / 4127 CC	GBC [®] AdvancedPunch [™] Integrated SquareFold® Oversized High Capacity 2 Tray Oversize High Ca Secure Access SW with Secure Access SW with Secure Access SW with SquareFold® Trimmer M XSIS Removable Hard Dri Opier/Printer (Market co	Full Service Maint. Plan Full Service Maint. Plan Full Service Maint. Plan CPC Only 1YR FSMA Trimmer Module Feeder pacity Feeder HID 125kHz Reader Magstripe Reader MiFare Reader Iodule ive – Install Kit ve – Extra Drive Kit des: 4112CP, P4112CP / 413	X9C1/1 X9H1/1 X9U1/1 X9G1/1 - - - - - - - - - - 27CP, P4127CP)	X201-7/1 X3H1-7/1 X1G1-7/1 - - - - - - - - - - - - - - - - - - -	298 793 1,150 1,300 65 50 60 75 11 10 11 50 30 15	- 125,000 200,000 200,000	.0059 .0062 .0045 .0029 - - - - - - - - - - - - - - - - - - -
P/4127EPS ADVPUNCH INTEGSFT OVRSZHCF OVRSZHCF2 SA-HID125 SA-HID125 SA-MAGSTR SA-MIFARE SQFOLDTRM XSISRH4C XSISED4C 4112 / 4127 CC	GBC [®] AdvancedPunch TM Integrated SquareFold® Oversized High Capacity 2 Tray Oversize High Ca Secure Access SW with Secure Access SW with Secure Access SW with Secure Access SW with SquareFold® Trimmer M XSIS Removable Hard Dri	Full Service Maint. Plan Full Service Maint. Plan Full Service Maint. Plan CPC Only 1YR FSMA Trimmer Module Feeder pacity Feeder HID 125kHz Reader Magstripe Reader MiFare Reader Iodule ive – Install Kit ve – Extra Drive Kit des: 4112CP, P4112CP / 412 Full Service Maint. Plan	X9C1/1 X9H1/1 X9U1/1 X9G1/1 - - - - - - - - - 27CP, P4127CP) X9L1/1	X201-7/1 X3H1-7/1 X1G1-7/1 - - - - - - - - - - - - - - - - - - -	298 793 1,150 1,300 65 50 60 75 11 10 11 50 30	- 125,000 200,000 200,000	.0059 .0062 .0045 .0029 - - - - - - - - - -
P/4127EPS ADVPUNCH INTEGSFT OVRSZHCF2 SA-HID125 SA-HID125 SA-MIFARE SQFOLDTRM XSISRH4C XSISED4C 4112 / 4127 CC	GBC [®] AdvancedPunch [™] Integrated SquareFold® Oversized High Capacity 2 Tray Oversize High Ca Secure Access SW with Secure Access SW with Secure Access SW with SquareFold® Trimmer M XSIS Removable Hard Dri Opier/Printer (Market co	Full Service Maint. Plan Full Service Maint. Plan Full Service Maint. Plan CPC Only 1YR FSMA Trimmer Module Feeder pacity Feeder HID 125kHz Reader Magstripe Reader MiFare Reader Iodule ive – Install Kit ve – Extra Drive Kit des: 4112CP, P4112CP / 413	X9C1/1 X9H1/1 X9U1/1 X9G1/1 - - - - - - - - - - 27CP, P4127CP)	X201-7/1 X3H1-7/1 X1G1-7/1 - - - - - - - - - - - - - - - - - - -	298 793 1,150 1,300 65 50 60 75 11 10 11 50 30 15	- 125,000 200,000 - - - - - - - - - - - - - - - - -	.0059 .0062 .0045 .0029 - - - - - - - - - - - - - - - - - - -

X9U1/1

X1G1-7/1

1,150

200,000

Full Service Maint. Plan



Equipment Sale & Maintenance

Price List reflects both Commercial and State/Local marketing segments

Equipment Maintenance Pricing

Billing Frequency: Commercial bills monthly in advance. State & Local bills monthly in arrears.

•	Only the	se accessories that	t carry a maintenand	e charge are indic	cated in the Main	tenance Price Lis
---	----------	---------------------	----------------------	--------------------	-------------------	-------------------

Market / Product Code	Component Description (All Configurations Unless Noted)	Service Plan Name	Maintenance Bill Code / Meter Ind X9G1/1	Lease Bill Code / Meter Ind X1A1-7/1	Monthly Base Charge \$ 1,300	Monthly Print Allowance 200,000	Charge Per Print
ADVPUNCH	GBC [®] AdvancedPunch [™]	•	-	-	65	-	.0020
INTEGSFT	Integrated SquareFold®		_	-	50	-	
OVRSZHCF	Oversized High Capacity		-	-	60	-	-
	2 Tray Oversize High Capacity		-	-	75	-	-
OVRSZHCF2 SA-HID125						-	-
SA-MAGSTR	Secure Access SW with		-	-	11	-	-
SA-MAGSTIK	Secure Access SW with	• .	-	-	10	-	-
SQFOLDTRM	Secure Access SW with		-	-	11	-	-
XSISRH4C	SquareFold® Trimmer Mode		-	-	50	-	-
	XSIS Removable Hard Dr		-	-	30	-	-
XSISED4C	XSIS Removable hard Dri		-	-	15	-	-
	2/4127 Print Server, por		1	les: 4112CP, P4		P, P4127CP)	[
EFICNTRL PEFICNTRL	Xerox EX 4112/4127 Print Server, powered by Fiery®	Full Service Maint. Plan	X981/0	-	50	-	-
NWT	FreeFlow [®] VI Design Pro)	-	-	40		-
VIGROUPA	FreeFlow [®] VI Compose		-	-	60	-	-
FreeFlow [®] Pr	int Servers for 4595/41	10/4112/4127	<u>.</u>		.	-	<u>t</u>
PDFFSVR PDSPSVR	FreeFlow [®] Print Server 4595	Full Service Maint. Plan	X981/0	-	100	-	-
IPDSW-7	IPDS Software License		-	-	125	-	-
LCDSSW	LCDS Software License		-	-	125	-	-
NWT	FreeFlow [®] VI Design Pro		_	-	40	-	-
VIGROUPA	FreeFlow [®] VI Compose		-	-	60	-	-
XSISRH4D	XSIS Removable Hard D	rive – Install Kit	-	-	60	-	-
XSISED4D	XSIS Removable hard Dr	ive – Extra Drive Set	-	-	30	-	-
OFCFFSVR LPFFSVR	FreeFlow [®] Print Server 4112/4127	Full Service Maint. Plan	X981/0	-	100	-	-
OFCLPSVR							
LPDSPSVR							
IPDSW	IPDS Software License		-	-	125	-	-
PDSW7	IPDS Software License		-	-	125	-	-
LCDSSW	LCDS Software License		-	-	125	-	-
NWT	FreeFlow [®] VI Design Pro		-	-	40	-	-
VIGROUPA	FreeFlow [®] VI Compose		-	-	60	-	-
DFFSVR DSPSVR	FreeFlow [®] Print Server 4595	Full Service Maint. Plan	X981/0	-	100	-	-
IPDSW	IPDS Software License		-	-	125	-	-
IPDSW6	IPDS Software License		-	-	125	-	-
LCDSSW	LCDS Software License		-	-	125	-	-
NWT	FreeFlow [®] VI Design Pro		-	-	40	-	-
VIGROUPA	FreeFlow [®] VI Compose		-	-	60	-	-



Equipment Sale & Maintenance

Price List reflects both Commercial and State/Local marketing segments

Equipment Maintenance Pricing

Billing Frequency: Commercial bills monthly in advance. State & Local bills monthly in arrears. •

 Only 	y those accessories that carr	y a maintenance charge are	e indicated in the Maintenance Price List.
--------------------------	-------------------------------	----------------------------	--

 Only those a 	accessories that carry a mainte						
Market / Product Code	Component Description (All Configurations Unless Noted)	Service Plan Name	Maintenance Bill Code / Meter Ind	Lease Bill Code / Meter Ind	Monthly Base Charge \$	Monthly Print Allowance	Charge Per Print
DSPCTRL PDSPCTRL	FreeFlow [®] Print Server 4595/4110	Full Service Maint. Plan	X981/0	-	100	-	-
IPDSW	IPDS Software License		-	-	125	-	-
IPDSW6	IPDS Software License		-	-	125	-	-
LCDSSW	LCDS Software License		-	-	125	-	-
NWT	FreeFlow [®] VI Design Pro)	-	-	40	-	-
VIGROUPA	FreeFlow [®] VI Compose		-	-	60	-	-
Xerox FreeFle	ow [®] Print Server 4595						
DFFSVR1 PDFFSVR1	Freeflow [®] Print Server 4595	Full Service Maint. Plan	X981/0	-	100	-	-
IPDSW-8	IPDS Software License		-	-	125	-	-
LCDSSW	LCDS Software License		-	-	125	-	-
NWT	FreeFlow [®] VI Design Pro)	-	-	40	-	-
VIGROUPA	FreeFlow [®] VI Compose		-	-	60	-	-
Xerox FreeFle	ow [®] Print Server 4112/	4127					-
OFFSVR1 LPFFSVR1	Freeflow [®] Print Server 4112/4127	Full Service Maint. Plan	X981/0	-	100	-	-
IPDSW-8	IPDS Software License	-	-	125	-	-	
LCDSSW	LCDS Software License	-	-	125	-	-	
NWT	FreeFlow [®] VI Design Pr	-	-	40	-	-	
VIGROUPA	FreeFlow [®] VI Compose		-	-	60	-	-
	-		-	<u>.</u>	•	-	÷
Xerox D136 P	Printer				_		-
D136PRT	D136 Printer	Full Service Maint. Plan	X961/1	XG61-6/1	0	-	.0060
		Full Service Maint. Plan	X971/1	XG71-6/1	75	-	.0040
		Full Service Maint. Plan	X941/1	X181-6/1	300	50,000	.0020
		Full Service Maint. Plan	X981/1	XG81-6/1	365	125,000	.0020
		Full Service Maint. Plan	X9E1/1	X6T1-6/1	450	200,000	.0020
OVRSZHF2	2 Tray Oversize High Capacity Feeder		-	-	75	-	-
STDFINPLS	Standard Finisher Plus		-	-	50	-	-
TAPE-BIND	Tape Binder		-	-	125	-	-
	rint Server for D95/110	/125/136	-		-	-	_
FFSVR	FreeFlow [®] Print Server D95/110/125	Full Service Maint. Plan	X961/0	-	50	-	-
FFSVR136	FreeFlow [®] Print Server D136	Full Service Maint. Plan	X981/0	-	50	-	-
LCDSSW	LCDS License		-	-	125	-	-
IPDSW1	IPDS SW License		-	-	125	-	-
NWT	FreeFlow [®] VI Design Pro		-	-	40	-	-
VIGROUPA	FreeFlow [®] VI Compose	-	-	60	-	-	
XSISRH4G	XSIS Removable Hard D	-	-	60	-	-	
XSISED4G	XSIS Removable hard Dr	-	-	30	-	-	



Equipment Sale & Maintenance Price List reflects both Commercial and State/Local marketing segments

Equipment Maintenance Pricing

Billing Frequency: Commercial bills monthly in advance. State & Local bills monthly in arrears.

	•	Only those ac	cessories that carry	y a mainten	ance charge are indicated in	the Maintenanc	e Price List.	
- 6								

Market / Product Code	Component Description (All Configurations Unless Noted)	Service Plan Name	Maintenance Bill Code / Meter Ind	Lease Bill Code / Meter Ind	Monthly Base Charge \$	Monthly Print Allowance	Charge Per Print		
Espresso Book Machine®									
 Solely with respect to the Customer's acquisition of the Espresso Book Machine (but not the 4112 copier/printer or any other Equipment): (a) the term Print Charges will apply to the number of books produced rather than the number of prints; (b) the Volume Band for Print Charges is determined by dividing the volume number by 100 (e.g., a Volume Band of 75,000 prints will mean 750 books); and (c) the Per Print Rate is determined by multiplying the rate by 100 (e.g., a Per Print Rate of \$0.015 will mean \$1.50). 									
ESPRESSO	Espresso Book	Full Service Maint. Plan	X9C1/1	X201-7/1	500	-	.0160		
	Machine®	Full Service Maint. Plan	X961/1	XG61-7/1	1,200	75,000	.0150		
		Full Service Maint. Plan	X971/1	XG71-7/1	1,700	130,000	.0139		
NO-WEBCAM No Web Cam Enablement VIGROUPA FreeFlow® VI Compose		-	-	1,800	-	-			
		-	-	60	-	-			



Light Production (D95-110-125-136) Price List

Effective: 11/01/2016 (Supersedes 07/01/2016)

Equipment Sale & Maintenance

Price List reflects both Commercial and State/Local marketing segments

Extended Service Coverage Option

Extended Service Coverage Options (Monthly Rates)

- Approval must be obtained from Local Service PRIOR to selling Extended Service Coverage on these Products
- Normal Coverage is 5 days per week, Monday Friday, one shift per day 8:00 a.m. to 5:00 p.m., except Xerox holidays.
- Additional levels of service coverage may be added to any existing Xerox Systems Services Agreements, Term Lease or Xerox Lease Agreement Contract. The original contract date will not be effected by the purchase of additional levels of coverage.
- The term of the coverage for the options will be the same as that contracted for the mainframe. If options are added at a later date, maintenance for options will expire on the same date as the mainframe.
- Holiday coverage is excluded from the Extended Service Offering.
- Extended Service Coverage is available in most areas as determined by Xerox Local Business Practices.
- Xerox may increase Extended Service Coverage charges by not more than ten percent (10%) per year.
- Extended Service Coverage charges as shown below, will be billed as follows:
 - Lease Agreements: Extended Service Coverage may not be added to the Service Component of the Lease. It will be on the Lease Agreement Meter Usage Invoice.
 - Xerox Systems Services Agreements: Extended Service Coverage will be added to the Monthly Base Charge.

Mon-Sat Mon-Sun Mon-Fri Mon-Sat Mon-Sun Mon-Fri Mon-Sat Mon-Sun Market Code/ Base 1 X 6 2 X 5 2 X 6 3 X 5 3 X 6 3 X 7 1 X 7 2 X 7 **Product Code** 8:00 AM 8:00 AM 8:00 AM 8:00 AM 8:00 AM 12:00 AM 12:00 AM Serv. 12:00 AM Cvrg. to to to to to to to to 5:00 PM 5:00 PM 12:00 AM 12:00 AM 12:00 AM 12:00 AM 12:00 AM 12:00 AM **Z16 Z11 Z20** Z25 Z22 Z30 Z36 Z33 140 320 510 420 495 D95CP, D110CP, D110PRT, 1 X 5 265 400 585 D125CP, D125PRT, D136CP, D136PRT EFISVR. EFISVR95. EFISVR136. 1 X 5 0 0 0 0 0 0 0 0 FFSVR, FFSVR136, FFSRVR, FFSRVR136 1 X 5 4112CP, P4112CP 4127CP, 140 320 265 400 510 420 495 585 P4127CP 4112EPS, P4112EPS 4127EPS, P4127EPS 4110, P4110, 1 X 5 140 320 265 400 510 420 495 585 4110CP, P4110CP 140 320 510 420 4595, P4595 1 X 5 265 400 495 585 4595CP, P4595CP 320 510 420 ESPRESSO 1 X 5 140 265 400 495 585 1 X 5 DFFSVR. DFFSVR1. DSPCTRL. 0 0 0 0 0 0 0 0 DSPSVR EFICNTRL, LPDSPSVR, LPFFSVR, LPFFSVR1, OFCFFSVR. OFCLPSVR, OFFSVR1, PDFFSVR, PDFFSVR1, PDSPSVR, PDSPCTRL, PEFICNTRL

Service Coverage Monthly Rates by Product (in dollars)