

**RECLAMATION –REMEDICATION BID
PACKAGE**

BID PACKAGE NO. 4

BID PACKAGE NUMBER 4

Reclamation-Remediation Clean-up Bid Package No. 4

COUNTY:

JASPER:

<u>WELL NAME</u>	<u>FIELD</u>	<u>API</u>	<u>LAT</u>	<u>LONG</u>
CHESTER BUXTON 1	HEIDELBERG	23-061-00288	31.916783	-89.004374
BUXTON 1-A	E. HEIDELBERG	23-061-20352	31.91532	-88.99065
LACKEY 1 UNIT 18-12	VERBA	23-061-20018	32.09882	-89.11603

JONES:

UNIDENTIFIED	BRYAN	-	31.79306	-88.952259
--------------	-------	---	----------	------------

WAYNE:

UNIDENTIFIED	CHAPPARAL	-	31.83001	-88.63074
--------------	-----------	---	----------	-----------

CLARKE:

UNIDENTIFIED	JUNCTION CITY	-	31.973758	-88.581956
UNIDENTIFIED	QUITMAN	-	32.0411	-88.648411

CLEANUP STATUS

Lat	Long	API # if any	Well Name if known	Well #	County	Field	Scope of Work	Package
31.916783	-89.004374	2306100288	CHESTER BUXTON	1	JASPER	Heidelberg	3 tanks , 2 treaters , concrete slabs , oily soil and pipe need to be removed, disposed and location restored.	4
31.91532	-88.99065	2306120352	BUXTON C	1-A	JASPER	Heidelberg E.	Pumping unit and slab remaining need to be removed, disposed and location restored.	4
32.09882	-89.11603	2306120018	LACKEY UNIT 18-12	1	JASPER	Verba	Old tanks and treater remaining need to be removed, disposed and location restored.	4
31.79306	-88.952259				JONES	Bryan	2- 500 bbl tanks with heavy crude on the ground outside the tanks. Tanks are located in the edge of a pine plantation with easy access. Need to be removed, disposed and location restored.	4
31.83001	-88.63074				WAYNE	Chapparral Field	5- 1000 bbl tanks that are in terrible shape and leaking in different spots around the bottom, a concrete pumping unit slab and old pipe and fitting need to be removed, disposed and location restored.	4
31.973758	-88.581956				Clarke	Junction City	2- 500 BBL tanks need to be removed, disposed and location restored.	4
32.0411	-88.648411				Clarke	Quitman	4- 1000 BBL tanks need to be removed, disposed and location restored.	4